

IMPORTANT RECALL NOTICE

(Expanded from the previous April 2012 Product Recall)

Tektro TL-83 Brake Levers

Sold from May 2011 to June 2012 on the 2012 S-Works Shiv Module and 2012 S-Works Shiv TT Modules



The brake levers can become non-functional, resulting in one or more of the brakes becoming non-operational, posing a crash hazard.

Please stop riding your bicycle immediately and return your levers/module/bicycle to an Authorized Specialized Retailer for free replacement brake levers.

If you have any questions, contact Specialized Bicycle Components Inc. at:

(877) 808-8154

or visit our web site at:

www.specialized.com